S.V Bewildered rigging, Mast refit including Chainplates and ProFurl





Halyard Swivel Bearing replaced with new seals Note: Lower swage and fittings



Upper Swage



Mast Painting with fittings removed as required for cosmetic correction and full servicing



Chainplates for the four(4) lower shrouds replaced. Upper shroud & backstay chainplates checked re-installed. Fasteners replaced as required and all sealed with caulking compound.



&
Two(2) upper shroud and backstay chainplates checked and re-installed
All chainplates 10mm in thickness



Chainplates fitted





Masthead

Spreader Detail



Stepping Mast





Mast Boot